

Safety Tag & Label Guide

Referenced Standard: ANSI/WCMA A100.1 - 2022 Standard for Safety of Window Covering Products

Bottom Rail Stickers - Tension Devices

 WARNING		Window Blind Cord Strangulation Risk <small>09/2023 ANSI/WCMA 5.1.1</small> A damaged, loose, or missing tension device poses a strangulation risk to children. Remove from use and repair or replace if tension device is damaged, loose, or missing.
		Riesgo de estrangulamiento por cordón de persiana <small>ANSI/WCMA 5.1.2</small> <small>09/2023</small> Un dispositivo de tensión dañado, suelto o faltante presenta un riesgo de estrangulamiento para niños. Retire y repare o reemplace si el dispositivo de tensión está dañado, suelto o falta.

Item#	HD91-0122-000001
Item Description	Bottom rail TD label 5.1.1 (2022), roll of 250
Actual Label Size:	8.5" x 1.25"
Addresses Section	5.1.1 ANSI/WCMA standards
Languages	English and Spanish

The label shall be a permanent marking affixed to all products with a Continuous Loop Operating System with a Tension Device. The label shall be placed on the bottom rail of the window covering. For products without bottom rails, the label shall be placed in an alternative location on the product, to be determined by the manufacturer or importer, that is visible to the user.

 WARNING		Window Blind Cord Strangulation Risk <small>ANSI/WCMA 5.1.2</small> <small>09/2023</small> A damaged, loose, or missing tension device poses a strangulation risk to children. Remove from use and repair or replace if tension device is damaged, loose, or missing.	 ADVERTENCIA		Riesgo de estrangulamiento por cordón de persiana <small>ANSI/WCMA 5.1.2</small> <small>09/2023</small> Un dispositivo de tensión dañado, suelto o faltante presenta un riesgo de estrangulamiento para niños. Retire y repare o reemplace si el dispositivo de tensión está dañado, suelto o falta.
---	---	---	--	---	--

Item#	HD91-0122-000002
Item Description	Bottom rail TD label 5.1.2 (2022), roll of 250, long
Actual Label Size:	15.25" x .55"
Addresses Section	5.1.2 ANSI/WCMA standards
Languages	English and Spanish

The label shall be a permanent marking affixed to all products with a Continuous Loop Operating System with a Tension Device. The label shall be placed on the bottom rail of the window covering. For products without bottom rails, the label shall be placed in an alternative location on the product, to be determined by the manufacturer or importer, that is visible to the user.

Bottom Rail Stickers - Single Retractable Cord Lift Systems

 WARNING		Window Blind Cord Strangulation Risk <small>09/2023 ANSI/WCMA 5.1.1</small> A retractable window blind cord that fails to fully retract poses a strangulation risk to children. Remove from use and repair or replace if cord fails to fully retract.
		Riesgo de estrangulamiento por cordón de persiana <small>ANSI/WCMA 5.1.2</small> <small>09/2023</small> Un cordón de persiana retráctil que no se retrae por completo presenta un riesgo de estrangulación para niños. Retire y repare o reemplace si el cable no se retrae por completo.

Item#	HD91-0121-000001
Item Description	Bottom rail CL label 5.1.1 (2022), roll of 250
Actual Label Size:	8.5" x 1.25"
Addresses Section	5.1.1 ANSI/WCMA standards
Languages	English and Spanish


The label shall be a permanent marking affixed to all products with a Single Retractable Cord Lift system. The label shall be placed on the bottom rail of the window covering. For products without bottom rails, the label shall be placed in an alternative location on the product, to be determined by the manufacturer or importer, that is visible to the user.

 WARNING		Window Blind Cord Strangulation Risk <small>ANSI/WCMA 5.1.2</small> <small>09/2023</small> A retractable window blind cord that fails to fully retract poses a strangulation risk to children. Remove from use and repair or replace if cord fails to fully retract.	 ADVERTENCIA		Riesgo de estrangulamiento por cordón de persiana <small>ANSI/WCMA 5.1.2</small> <small>09/2023</small> Un cordón de persiana retráctil que no se retrae por completo presenta un riesgo de estrangulación para niños. Retire y repare o reemplace si el cable no se retrae por completo.
---	---	--	--	---	---

Item#	HD91-0121-000004
Item Description	Bottom rail CL label 5.1.2 (2022), roll of 250, long
Actual Label Size:	15.25" x .55"
Addresses Section	5.1.2 ANSI/WCMA standards
Languages	English and Spanish

The label shall be a permanent marking affixed to all products with a Single Retractable Cord Lift system. The label shall be placed on the bottom rail of the window covering. For products without bottom rails, the label shall be placed in an alternative location on the product, to be determined by the manufacturer or importer, that is visible to the user.


Hang Tags - Tension Devices



The warning tag shall be used on all window covering products that have Tension Devices (attached to Cord or Tension Device).

Item#	HD91-0106-000001
Item Description	Tension device tag 5.2.1 (2022)
Actual Label Size:	2.75" x 5.75" (large hole on top)
Addresses Section	5.2.1 ANSI/WCMA standards
Languages	English and Spanish (two sided)

Hang Tags - Single Retractable Cord Lift Systems



The warning tag shall be used on all window covering products that utilize a Single Retractable Cord Lift system.

Item#	HD91-0123-000001
Item Description	Single Retractable Cord Lift tag 5.2.2 (2022)
Actual Label Size:	2.75" x 6.25" (large hole on top)
Addresses Section	5.2.2 ANSI/WCMA standards
Languages	English and Spanish (two sided)

ROLLEASE ACMEDA IS COMMITTED TO CHILD SAFETY

Use this quick reference guide to help identify which warning tags or labels offered by Rollease Acmeda are right for your application. If you have any questions or would like to place an order for a warning tag/label or other Rollease Acmeda ChildSafe products, please contact us on 800 552 5100 or via email at sales@rolleseeacmeda.com.