

Tel +1 717 764 7700 Fax +1 717 764 4129 intertek.com

May 22, 2024

ROLLEASE ACMEDA 750 East Main Street 7th Floor Stamford, Connecticut 06902

RE: Letter of Conformance for Job No. 09575.01-106-31

Testing was recently performed by Intertek¹ Building & Construction (B&C) on Beaded Chain/Cord Operable Window Shade, Tension Device with Mounting Components at the Intertek test facility in York, PA.

The materials were provided by Rollease Acmeda. The following were received in good condition on 1/5/24:

- Four (4), Window rollers consisting of two sizes with associated mounting hardware
- Five (5), Black tension devices (RB91-1336-xxx000 Chainhold Cover and RB91-1337xxx000 Chainhold Base Assembly)
- Five (5), Clear tension devices (RB91-1336-xxx000 Chainhold Cover and RB91-1337xxx000 Chainhold Base Assembly)
- Five (5), Outside mounting brackets (RB91-1338-001110 Chainhold Mounting Kit)
- Five (5), Floor mounting brackets (RB91-1338-001210 Chainhold Floor Fix Bracket)
- Five (5), Side mounting brackets (RB91-1338-001310 Chainhold Side Fix Bracket)
- Two (2), Metal beaded chain/cord
- Three (3), Plastic and cloth beaded chain/cord each with tension devices attached.
- Two (2), sets of installation instructions

The test specimens were evaluated in accordance with ANSI/WCMA A100.1-22, Safety of Corded Window Covering Products and found to be in conformance with the standard.

Complete test specimen descriptions and test data can be found in report #Q9575.01-106-31-R1. If you have any questions, please feel free to contact me at your convenience. This document is a letter of conformance, it is not a test report.

Version: 10/20/22 Page 1 of 2 O-R-AMER-Test-7809



¹ Intertek is a brand name representing the Intertek Group plc legal entities, including but not limited to, Intertek Testing Services NA Inc., Professional Service Industries, Inc. ("INTERTEK-PSI"), Architectural Testing Inc. ("INTERTEK-ATI"), and MT Group Inc. ("INTERTEK-MT").

This Letter of Results (LOR) is for the exclusive use of Intertek's Client and is provided pursuant to the agreement between Intertek and its Client. Intertek's responsibility and liability are limited to the terms and conditions of the agreement. Intertek assumes no liability to any party, other than to the Client in accordance with the agreement, for any loss, expense or damage occasioned by the use of this LOR. Only the Client is authorized to permit copying or distribution of this LOR and then only in its entirety. Any use of the Intertek name or one of its marks for the sale or advertisement of the tested material, product or service must first be approved in writing by Intertek. The observations and test results in this LOR are relevant only to the sample(s) tested. This LOR by itself does not imply that the material, product, or service is or has ever been under an Intertek certification program.

Mr. Matthew Weitz Q9575.01-106-31-LOR Page 2 of 2 May 22, 2024

Sincerely, INTERTEK B&C

Todd M. Welch Technician I Materials Laboratory

TMW:jmb

cc: Q9575.01-106-31-LOR

Joseph M. Brickner Technical Manager Materials Laboratory